





UNIA EUROPEJSKA

Laboratorium doposażone ze środków Europejskiego Funduszu Rozwoju Regionalnego

i Wyrobów Włókienniczych Siedziba: ul. Brzezińska 5/15, 92-103 Łódź, tel. +48(0) 42 6163140 Siedziba: ul. Gdańska 118. 90-520 Łódź. tel. +48(0) 42 2534421

Laboratorium Badań Surowców

## POLSKIE CENTRUM AKREDYTACJI BADANIA AB 164

## ŚWIADECTWO Z BADAŃ NR BM 2.13.1.1/2015/B/A

- 1. Nazwa i adres Zleceniodawcy: "TOPTEXTIL" Sp. z o.o. ul. Wadowicka 12; 30-415 Kraków
- 2. Nazwa i opis przedmiotu badań: próbka: tkanina obiciowa meblowa REAL, deklarowany skład surowcowy: 100% PES
- 3. Data otrzymania przedmiotu do badań: 25.08.2015
- 4. Data wykonania badań: 02 .09.2015
- 5. Próbki pobrano: próbka o wielkości prawidłowej, w stanie właściwym do badań, pobrana przez Zleceniodawcę i dostarczona bez Protokołu z poboru próbek.
- 6. Badania wykonano zgodnie z: metodami badań podanymi w zestawieniu wyników

#### Zestawienie wyników badań laboratoryjnych

patrz: strona 2/2


Badania wykonała: Danuta Ławniczak

- 1. Wyniki badań dotyczą wyłącznie przedmiotu badanego.
- 2. Bez pisemnej zgody Kierownika Laboratorium Świadectwo z badań nie może być powielane fragmentarycznie lecz tylko w całości.
- 3. Świadectwo z badań zawiera wyniki badań objętych zakresem akredytacji.
- 4. Wyniki badań nie objętych zakresem akredytacji, jeśli występują, oznaczono symbolem \*) umieszczonym w tabeli wyników przy nazwie wskaźnika.
- 5. Niepewność pomiaru, jeśli jest określona, została wyznaczona zgodnie z zaleceniami zawartymi w dokumencie EA-4/16. Podane wartości niepewności stanowią niepewność rozszerzoną przy poziomie ufności 95% i współczynniku rozszerzenia k=2.

#### Data sporządzenia świadectwa: 03.09.2015 Liczba egzemplarzy świadectwa: 2 Świadectwo z badań otrzymuja:

- 1) TOPTEXTIL Sp. z o.o., Kraków 1 egz.
- 2) IW Laboratorium Badań Surowców i Wyrobów Włókienniczych 1 egz. a/a

Swiadectwo sporzadzila: Elżbieta Piekarek-Kubicka



Funkcja: Laboratoriu dań Surowców i Wyrobó Podpis kienniczych Instytu kiennictwa mgr inż. Halina Królikowska



INSTYTUT WŁÓKIENNICTWA Laboratoriulm Badań Surowców WARDOW Włókienniczych 21. Brzezińska T Łódź. 92-103 {

verte-

## ŚWIADECTWO Z BADAŃ NR BM 2.15.2.1/2015/B/A

Wskaźnik	Wartość	Metoda badania
Odporność na przesunięcie w szwie		PN-EN ISO 13936-2:2005
Osnowa		Warunki pomiarów:
Średnia wartość prześwitu w szwie	4	maszyna wytrzymałościowa Hounsfield H50 KM,
dla kierunku wzdłużnego, mm		wartość zastosowanej siły: 180 N,
- poszczególne wyniki pomiarów, mm	3,5; 3,5; 4; 4; 4	nici szwalne: 100% poliester rdzeniowy (74±5) tex
	5,5, 5,5, 1, 1, 4	igła o numerze: 110
Watek		ilość ściegów: 32±2/100 mm
Średnia wartość prześwitu w szwie	5	prędkość rozciągania 50 mm/min.
dla kierunku poprzecznego, mm	5	liczba próbek roboczych: 5
- poszczególne wyniki pomiarów, mm	5; 4,5; 4,5; 4,5; 4,5	
Ocena:		
wg PN-EN 14465:2005+A1:2007		
morion wymagań: kategoria A < 4 mm. 1		

poziom wymagań: kategoria A  $\leq 4$  mm; kategoria B  $\leq 6$  mm; kategoria C  $\leq 8$  mm

Koniec Świadectwa z badań

Osoba autoryzująca Świadectwoz badań

Laboratorium Badań Surowców i Wyrobów Włókienniczych Instrutt/Włókiennictwa (rotikowska m

## ŚWIADECTWO Z BADAŃ NR BM 2.15.2.2/2015/B/A

	Wartość	Metoda badania	
liczba suwów 500	5	PN-EN ISO 12945-2:2002 (zmodyfikowana metoda Martindale <i>Warunki badania:</i> ścieracz: standardowa tkanina wełniana;	
1 000	5		
2 000	4 - 5 lekkie zmechacenie	stosowane obciążenie: $415 \pm 2$ g;	
	500 1 000	liczba suwów 500 5 1 000 5 <b>2 000 4 - 5</b>	

kategoria C: stopień 3 – 4; kategoria D: stopień 3

Koniec Świadectwa z badań \_\_\_\_

Osoba autoryzująca Świadectwo z badań Kierownik Laboratorium Badań Surowców i Wyrobów Włókienniczych Instydut/Wokiennictwa mgr inż. Halina Królikowska

Wskaźnik		Wartość	Metoda badania
	zmiana barwy po 3 000 suwów, stopień szarej skali	4 - 5	PN-EN ISO 12947-2:2000+ AC:2006 + PN-EN 14465:2005+A1:2007, Załącznik A Warunki pomiarów
Odporność na ścieranie, liczba suwów	1 próbka	100 000 brak całkowitego zniszczenia	ścieracz: standardowa tkanina wełniana, obciążenie: 12 kPa, urządzenie powiększające o współczynniku
	2 próbka	100 000 brak całkowitego zniszczenia	powiększenia 8, w uchwytach stosowano podkładkę z pianki. kryterium zniszczenie próbki wg ww. normy:
	3 próbka	100 000 brak całkowitego zniszczenia	co najmniej trzy nitki całkowicie zniszczone
	4 próbka	100 000 brak całkowitego zniszczenia	
	<b>Ogólna odporność</b> <b>na ścieranie</b> (najniższy pojedynczy wynik)	<b>100 000</b> brak całkowitego zniszczenia	

## ŚWIADECTWO Z BADAŃ NR BM 2.15.2.3 / 2015 / B / A

\_ Koniec Świadectwa z badań

Osoba autoryzująca Świądectwo z badań Kienownik Laboratorium Badań Surowców i Wyrobów Włókienniczych Ins Outrytokiennictwa Insty mgr inż. Halina Królikowska

## **TECHNICAL REPORT**



Maxwell Road, Stevenage Hertfordshire SG1 2EW, UK

> T: +44(0) 1438 777 700 F: +44(0) 1438 777 800 E: info@fira.co.uk W: www.fira.co.uk

Our Ref: TFFLF61547 Date: 20 October 2015 Delivery Date: 25 September 2015 Test Dates: 12 - 19 October 2015

**Toptextil Sp Z.o.o** UI Wadowicka 12 Krakow 30-415 Poland

For the attention of Magdalena Jaworska

#### SAMPLE(S) FOR TEST:

One, Fabric - Ref: ROYAL

Note: The above descriptions are as supplied by the client and have not been verified by FIRA who can take no responsibility for the accuracy of the description.

### **TEST REQUIREMENTS:**

Schedule 4 part I (based on BS 5852: 1979 Part 1) Schedule 5 part I (based on BS 5852: 1979 Part 1)

The material was subjected to the water soak procedure and line dried as detailed in The Furniture and Furnishings (Fire) (Safety) Regulations 1988, amended 1989, 1993 and 2010.

FIRA is a UKAS TESTING Laboratory No. 0174

Tests marked "Not UKAS Accredited" in this Report are not included in the UKAS Accreditation Schedule for our laboratory.

Opinions and interpretations expressed herein are outside the scope of UKAS Accreditation.

This Report relates to the sample(s) submitted for test and no others. Additions, deletions or alterations are not permitted.

Test reports are given to the client in confidence, and may only be reproduced in whole or in part with written permission from FIRA International Limited. Note that the words "tested by FIRA" may be used in subsequent publicity for the product; "approved" must not be used.

Tests are carried out on the understanding that neither FIRA International Limited nor its officers can accept any legal responsibility for information or advice given or opinions expressed whether in response to specific enquiries or otherwise.

This Report is given subject to the Terms of Business of FIRA International Limited which are available at www.fira.co.uk/document/fira-terms-andconditions.pdf



TFFLF61457 Page 1 of 3

FIRA International Ltd Registered office: 6 Coronet Way, Centenary Park, Eccles, M50 1RE, UK Registered in England No: 3181481

## **RESULT:**

Pass Pass

## **TECHNICAL REPORT**

### DESCRIPTION

Enquiry No: TFFLF61547

Item: One, Fabric - Ref: ROYAL

The following test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.

#### TEST RESULTS

# FURNITURE AND FURNISHINGS (FIRE) (SAFETY) REGULATIONS 1988 - AMENDED 1989, 1993 AND 2010 SCHEDULE 4 PART 1 MODIFICATION TO BS 5852: PART 1 THE CIGARETTE TEST

Conditioning: ≥3 days at indoor ambient conditions and ≥16 hours at 20±5°C & 50±20% rh

Initial Inspection: Condition as new

Test conditions: 21.6°C & 49.0% rh

Filling material: A conventional urethane foam of nominal density 20-22kgm<sup>3</sup> Ref: VP45, and an 85g thermally bonded polyester fibre wrap.

Test procedure - as defined in Schedule 4 part 1 of the above Regulations.

	nition ource	Ignition/ Non- Ignition	Duration of		
No.	Pos.		Ignition Source	Flames	Smoke/ Smoulder
0	1	PASS (N/I)	14min 39sec	N/A	17min 46sec
	2	PASS (N/I)	14min 00sec	N/A	17min 08sec

#### COMMENTS

Local charring of the cover occurred in the area immediately surrounding the cigarette. The cover char remained intact throughout the test. The final examination showed the underlying filling to be damaged only superficially.

#### CONCLUSION

This composite passes the test specified in Schedule 4 Part 1 of The Furniture and Furnishings (Fire) (Safety) Regulations 1988 - Amended 1989, 1993 and 2010.





## **TECHNICAL REPORT**

# FURNITURE AND FURNISHINGS (FIRE) (SAFETY) REGULATIONS 1988 - AMENDED 1989, 1993 AND 2010 SCHEDULE 5 PART 1 THE MATCH TEST (BASED ON BS 5852: 1979 PART 1)

Item: One, Fabric - Ref: ROYAL

Conditioning: ≥3 days at indoor ambient conditions and ≥16 hours at 20±5°C & 50±20% rh

Initial Inspection: Condition as new

Test conditions: 22.4°C & 48.8% rh

Test procedure - as defined in Schedule 5 part 1 of the above Regulations using specified non fire-retardant polyurethane foam 20-22kg/m<sup>3</sup>.

	nition ource	Ignition/ Non- Ignition	Duration of		
No.	Pos.		Ignition Source	Flames	Smoke/ Smoulder
1	1	PASS (N/I)	20sec	27sec	31sec
	2	PASS (N/I)	20sec	22sec	25sec

#### COMMENTS

On contact with the ignition source the cover material melted open slightly and ignited briefly, partially exposing the underlying filling. The partially exposed filling melted but did not ignite. Final examination showed that all materials were damaged.

### CONCLUSION

This fabric sample passes the test specified in Schedule 5 Part 1 of The Furniture and Furnishings (Fire) (Safety) Regulations 1988 - Amended 1989, 1993 and 2010.

- Tested by: Barry Worrell
- Reported by: Matthew Carey
- Approved by: Liz Morey Technical Specialist





